# **U.S. Department**

# of Transportation

United States Coast Guard

## LOCAL NOTICE TO MARINERS

JUNE WEEKLY SUPPLEMENT

## **NOTICE NUMBER 23-97**

June 03, 1997

Issued by: Commander, Seventh Coast Guard District (oan)

Brickell Plaza, Federal Building 909 S.E. 1<sup>st</sup> Avenue, Miami, Florida 33131-3050 Telephone (305) 536-5621 (Office hours 7:30 a.m. - 4:00 p.m., M-F)

#### **BROADCAST NOTICE TO MARINERS**

Navigation information having been of immediate concern to the Mariner, and promulgated by the following broadcasts, has been incorporated in this notice when still effective:

- CCGD7 (D7) BNM 558-97 TO 591-97
- GROUP CHARLESTON (CHA) BNM 272-97 TO 296-97
- GROUP MAYPORT (MAY) BNM 323-97 TO 342-97
- GROUP MIAMI (MIA) BNM 272-97 TO 291-97
- GROUP KEY WEST (KEY) BNM 071-97
- GROUP ST. PETERSBURG (STP) BNM 340-97 TO 370-97
- SAN JUAN (SJ) BNM 211-97 TO 222-97

NOTES: (1) Unless otherwise indicated, missing and destroyed structures are presumed to be in the immediate vicinity. Mariners should proceed with caution.

- (2) A dark vertical line in the left margin indicates new information.
- (3) The Local Notice to Mariners consists of a Monthly Edition and Weekly Supplementals. The Monthly Edition should be maintained as a reference. Recurring information is published only once a month.

REFERENCES:Light List, Vol. III, Atlantic and Gulf Coasts, 1996 Edition (COMDTPUB P16502.3).

U.S. Coast Pilot 4, Atlantic Coast: Cape Henry to Key West (3<sup>§t</sup> Edition).

U.S. Coast Pilot 5, Atlantic Coast: Gulf of Mexico, Puerto Rico, and Virgin Islands (26 Edition).

\* \* \* \* \* \* \* \*

# REPORT DISCREPANCIES IN AIDS TO NAVIGATION TO THE NEAREST COAST GUARD UNIT

\* \* \* \* \* \* \* \* \*

#### I. SPECIAL NOTICE

## SLOW SPEED ZONES/NATIONAL PARK SERVICE

Biscayne National Park has extended the deadline for public comment on proposed slow speed zones in the vicinity of the Safety Valve and Sands and Elliott Keys in order to accommodate those who may have missed the original deadline. The new date is June 27, 1997. Additionally, a public meeting on the proposal will be held at 7:00 p.m. on July 23 at the Biscayne National Park Visitor Center Auditorium, 9700 SW 328 Street in Homestead.

The idea for the speed zones was proposed by a South Dade boating club in order to address safety concerns in and around popular anchorages near the parks islands. Many are in support of the entire proposal and several have indicated that the proposal does not go far enough in protecting park resources. At the opposite end of the spectrum, many feel that better ways to deal with the problems are to increase enforcement of existing regulations, increase marking of the shallow areas for resource protection, and increase boater education efforts, including operator licensing.

On a typical weekend the areas included in the proposal host scores of boaters engaged in a variety of activities, including swimming, snorkeling, water skiing, fishing, and personal watercraft use. Many of these activities are incompatible with one another and have led to serious personal injury and property damage. The proposal's primary objectives are to decrease the threat of serious vessel accidents, to increase visitor safety by providing a safer area for anchored vessels and in-water recreational activities, to seperate incompatible water-based recreational activites, and to protect shallow seagrass habitat.

Written comments on the proposal should be direct to: Superintendent; Biscayne National Park; P.O. Box 1369; Homestead, Florida 33090-1369.

## **EXCERPT FROM FEDERAL REGISTER ARTICLE -**

#### Inflatable Liferafts

The following information is an excerpt of Federal Register, Vol. 62, No. 90, Friday, May 09, 1997, Pages 25525 - 25557.

Agency: Coast Guard, DOT. Action: Final rule.

Summary: The Coast Guard is revising its regulations for the approval and servicing of inflatable liferafts, and adding provisions for the approval of inflatable buoyant apparatuses. This final rule implements the 1983 Amendments to the International Convention for the Safety of Life at Sea, 1974 (SOLAS), adds provisions for approval of a new "Coastal Service" liferaft for use on certain uninspected fishing vessels, introduces requirements for the stability of liferafts, and reduces direct Coast Guard involvement in inspections of liferaft production and servicing. This final rule will bring liferafts approved by the Coast Guard into compliance with SOLAS, improve the seaworthiness of approved liferafts, and increase manufactures' flexiblity in scheduling liferaft inspections while reducing the associated burden on the Coast Guard.

Dates: This final rule is effective June 09, 1997. The incorporation by reference of certain publications listed in the rule is approved by the Director of the Federal Register on June 09, 1997.

Addresses: Documents as indicated in this preamble are available for inspection or copying at the office of the Executive Secretary, Marine Safety Council (G-LRA/3406), U.S. Coast Guard Headquarters, 2100 Second Street SW., room 3406, Washington, DC 20593-0001 between 9:30 a.m. and 2 p.m., Monday through Friday, except Federal holidays. The telephone number is (202) 267-1477.

For Further Information Contact: Mr. Kurt J. Heinz, Lifesaving and Fire Safety Standards Division (G-MSE-4), U.S. Coast Guard Headquarters, 2100 Second Street SW., Washington, DC 20593-0001, telephone number is (202) 267-1444, fax (20) 267-1069, E-Mail "kheinz@comdt.uscq.mil.

## II. NEW DISCREPANCIES-DISCREPANCIES CORRECTED

The following is a partial list of aids that were not watching as advertised in the Light List as of 1:00 a.m. on the date of this Notice and a list of aids previously reported discrepant that have been corrected since the last Local Notice to Mariners. Unless otherwise indicated, missing and destroyed structures are presumed to be in the immediate vicinity. Mariners should proceed with caution. For a complete list of discrepancies and for descriptions of abbreviations see Monthly Local Notice to Mariners 22-97.

# FEDERAL AID DISCREPANCIES:

LLNR	AID NAME	DISCREPANCY	′	CHARTBNM	LNM			
01500 23/97	Winyah Bay C	h LT 19		TRLB		11532	284-97	-CHA
02215 23/97	Town Cr Ch Ll	B 2	OFF S	TA		11524	294-97	-CHA
03140	Folly Riv DBN		TRUB			283-97		23/97
03265	N Edisto Riv E		LT IMC		11522	285-97	-CHA	23/97
06220 23/97	Cumberland S	nd Lower Rng C	RFL	LT DIM		11503	342-97	-MAY
07230	Forrester Pt L		LT EX1		11492	338-97	-MAY	23/97
07285	Rice Cr Ent Cl	h RFL		LT EXT		11492	337-97	-MAY
23/97								
19335	Longboat Pass	s DBN 3		DBN DEST			11425	353-
97-STP								
20025	Pt Manatee Cl	h LB 6		LT EXT		11414	352-97	-STP
23/97								
20095	Tampa Bay Cu	ut C Ch LB 5C		LT DIM		11414	370-97	-STP
23/97					44440		0.70	00/07
20675	Alafia Riv DBN		TRLB	TOUD	11413	350-97		23/97
27170	Keaton Beach	DBN 4A		TRUB		11407	N/A	
23/97	Dahia da Over	.a.a.illa LD4		OFF OTA			05004	04.4
28515	Bahia de Guay 23/97	yanilia LB 1		OFF STA			25681	214-
97-GSE		DDN 50		TDLID		11510	270.07	СПУ
32605 23/97	Skidaway Riv	DDN 92		TRUB		11512	278-97	-СПА
34165	Cumbarland S	nd Lower Rng C	DEI	LT DIM		11502	342-97	MAV
23/97	Cullibeliallu S	THE LOWER KING C	IXEL	LI DIIVI		11503	342-37	-IVI <i>I</i> -\ I
34560	Sawpit Cr LT 4	49	TRLB		11489	332-97	-MAY	23/97

Matanzas Riv DBN 55	TRUB		11485 339-97	-MAY
Fox Cut Lt 3	TRLB	11485	333-97-MAY	23/97
Halifax Riv DBN 4	TRUB	11485	330-97-MAY	23/97
Indian Riv N Sec DBN 101	TRUB		11472 341-97	-MAY
Indian Riv S Sec DBN 144	TRUB		11472 287-97	-MIA
Lake Worth S DBN 2	TRUB		11472 282-97	-MIA
Woods Pt DBN 3	TRUB	11472	291-97-MIA	23/97
	Fox Cut Lt 3 Halifax Riv DBN 4 Indian Riv N Sec DBN 101 Indian Riv S Sec DBN 144 Lake Worth S DBN 2	Fox Cut Lt 3 Halifax Riv DBN 4 Indian Riv N Sec DBN 101 TRUB Indian Riv S Sec DBN 144 TRUB Lake Worth S DBN 2 TRUB	Fox Cut Lt 3 Halifax Riv DBN 4 Indian Riv N Sec DBN 101 TRUB Indian Riv S Sec DBN 144 TRUB TRUB TRUB TRUB TRUB TRUB	Fox Cut Lt 3 TRLB TRUB 11485 333-97-MAY 11485 330-97-MAY 11485 330-97-MAY 11472 341-97 Indian Riv S Sec DBN 144 TRUB 11472 287-97 Lake Worth S DBN 2 TRUB 11472 282-97

# FEDERAL DISCREPANCIES CORRECTED:

LLNR	AID NAME STAT	ΓUS	CHART	BNM	LNM				
00155	Charleston Navy Tes 23/97	st LB TB		WATC	HING P	ROPER	LY	11523	N/A
00630 23/97	Fowey Rocks LT		WATC	HING F	ROPERI	_Y	11465	274-97	-MIA
03130 23/97	Folly Riv LT 9		WATC	HING F	ROPERI	_Y	11522	N/A	
06330 23/97	Kings Bay LT 52		WATC	HING F	ROPERL	_Y	11503	331-97	-MAY
06460 97-MA		3		WATC	HING P	ROPER	LY	11490	334-
09365 23/97	Pt Everglades Ent R	RL		RELIG	HTED		11470	275-97	-MIA
09390 09950 23/97	Pt Everglades LT 9 Elliott Key LT 20				ROPERI			N/A	23/97
19415	Manatee Riv DBN 10 23/97	)		REBU	ILT/REC	OVERE	D	11425	N/A
19490		6		REBU	ILT/REC	OVERE	D	11425	240-
20025 97-STP	Pt Manatee Ch LB 6			WATC	HING P	ROPER	LY	11414	366-
	Tampa Bay Cut D C	h LBB 5D		RELIG	HTED		11412	340-97	-STP
28745	Canal de la Mona E 22/97	ShI LB 6		WATC	HING P	ROPER	LY	25671	N/A
32695 97-CH	Vernon Riv DBN 82 15/97			REBU	ILT/REC	OVERE	D	11512	135-
32970 97-CHA	N Newport Riv LT 12	23		WATC	HING P	ROPER	LY	11511	268-
33090 33180 97-MA	Front Riv LT 153 Old Teakettle Cr DB	N 168	RELIG		ILT/REC		276-97 D	-CHA 11510	
	Halifax Riv DBN 46		WATC	HING F	ROPERI	_Y	11485	322-97	-MAY
	Indian Riv N Sec DB 23/97	N 86		WATC	HING P	ROPER	LY	11485	326-
38740				WATC	HING PI	ROPER	LY	11476	N/A

40940 97-MIA				WATCHING PROPERLY				11472	286-
43440				RELIGH	RELIGHTED 11467			276-97-MIA	
	Lake Okeechobee LT 1			RELIGH	ITED		11428	362-97	-STP
23/97 LLNR	AID NAME	STATUS	CHART	ΓBNM L	_NM				
58490 97-STP		ampa Bay DBN 8	8A	REBUIL	T/REC	COVERE	D	11425	338-
59120	Siesta Key-Tampa Bay DBN 24			REBUIL	REBUILT/RECOVERED				265-
97-STP 59995	Siesta Key-T	ampa Bay DBN 5	60	REBUIL	T/REC	COVERE	D	11425	261-
97-STP 61395			REBU	ILT/RECO	OVERE	ĒD	11411	239-97-STP	
16/97 61875	St Joseph Sr 23/97	nd DBN 7		REBUIL	T/REC	COVERE	D	11411	N/A
PRIVAT	TE AID DISCR	REPANCIES:							
LLNR	AID NAME	DISCREPANC	Y	CHARTE	BNM	LNM			
	*Weedon Isla	and Ch LB 7		MISSIN	G			11413	359-
97-STP 42408	*Boat Club P	7 ark Ch DBN 3		DBN DN	ИGD			11467	N/A
43115	23/97 *Keystone Pt	t Ch DBN 4		DBN DN	ИGD			11467	N/A
43120	23/97 *Keystone Pt	t Ch DBN 6		DBN DN	ИGD			11467	N/A
43125	23/97 *Keystone Pt	t Ch DBN 8		DBN DN	ИGD			11467	N/A
43130	23/97 *Keystone Pt	t Ch DBN 10		DBN DN	ИGD			11467	N/A
43135	23/97 *Keystone Pt			DBN DN	/GD			11467	N/A
43140	23/97 *Keystone Pt			DBN DN				11467	
43145	23/97 *Keystone Pt			DBN DN				11467	-
49975	23/97 *Matlacha Pa			DBN DN				11426	
49975	23/97	355 DBN 02		DBN DN	NGD			11420	IN/A
PRIVAT	TE DISCREPA	ANCIES CORREC	CTED:						
LLNR	AID NAME	STATUS	CHART	ΓBNM L	_NM				
05680 50/96	*Colonels Island RFL WATCI			HING PR	OPER	RLY	11506	?	
25615		er Corporation Ch	LT 23	WATCH	IING P	ROPER	LY	11408	N/A
25665		er Corporation Ch	LT 35	WATCH	IING P	ROPER	LY	11408	N/A
25725 97-STP		er Corporation Ch 7	LT 47	WATCH	IING P	ROPER	LY	11408	050-

25755 97-STP	*Florida Power Corporation Ch LT 55 10/97	WATCHING PROPERLY	11408	117-
25760 97-STP	*Florida Power Corporation Ch LT 56 10/97	WATCHING PROPERLY	11408	117-
42407	*Boat Club Park Ch DBN 1 06/97	WATCHING PROPERLY	11467	N/A
43480	*Miami Shores Ch DBN 2 04/97	WATCHING PROPERLY	11467	N/A
43485	*Miami Shores Ch DBN 4 04/97	WATCHING PROPERLY	11467	N/A
43500	*Miami Shores Ch DBN 10 04/97	WATCHING PROPERLY	11467	N/A
43505	*Miami Shores Ch DBN 12 04/97	WATCHING PROPERLY	11467	N/A
	*Safety Hbr Ch DBN 2 06/97	WATCHING PROPERLY	11426	N/A
50740	*Safety Hbr Ch DBN 3 06/97	WATCHING PROPERLY	11426	N/A
50745	*Safety Hbr Ch DBN 4 06/97	WATCHING PROPERLY	11426	N/A
50765	*Safety Hbr Ch DBN 14 06/97	WATCHING PROPERLY	11426	N/A

# III. TEMPORARY CHANGES-AIDS ESTABLISHED:

LLNR AID NAME STATUS CHARTBNM LNM

Pg 421 Clearwater Hbr DBN 18A EST/Shl 11411 351-97-STP 23-97

# **TEMPORARY AIDS CORRECTED:**

LLNR AID NAME STATUS CHARTBNM LNM

None.

# IV. CHART CORRECTIONS

(Explanation of Format)

Corrective action, affecting charts, is contained in this section. Chart corrections are listed numerically by chart number, beginning with the lowest and progressing through all charts affected. The correction listed pertains to that chart only. It is up to the mariner to decide which charts are to be corrected. The following example explains the individual elements of a typical correction.

	Chart Chart Edition		n Last Local Not	Last Local Notice		Source of	Current
Notice							
	number	edition date	to Mariners	datum	correction	to Mariners	
	1 . 1						
11534	26 <sup>th</sup> ed.	12/14/91	 Last LNM 41/9	2	NAD 8	3(CG7) 06/93	
(Temp)	Myrtle G	rove Sound to	Fear River to C	asino Cr	eek	, ,	
,	Add I	Boguse Chan	nel Light 1, Fl G	2.5s, 16	ft, 7M		
	32 <sup>2</sup> 48′00″N 79 <sup>2</sup> 15′00″W						
	:						

Corrective Object of corrective Position action

The letter (M) immediately following the chart number indicates that the correction should be applied to the metric side of the chart only. (Temp) indicates that the chart correction action is temporary in nature. Courses and bearings are given in degrees clockwise from 000 true. Bearings of light sectors are toward the light from seaward. The nominal range of lights is expressed in nautical miles (M).

1114 A 30<sup>th</sup> ed., 10/12/96 LAST LNM 21/97 NAD 83 23/97 Tampa Bay to Cape San Blas (CGD07) **CHANGE** Champion Reef Center Buoy to Y can in (Priv maint) 28236'04.5"N 082256'05.0"W (Supersedes LNM 21/97) 11400 30<sup>th</sup> ed., 10/12/96 LAST LNM 21/97 NAD 83 23/97 Tampa Bay to Cape San Blas (CGD07) CHANGE Champion Reef Center Buoy to Y can in (Priv maint) 28<sup>2</sup>36'04.5"N 082<sup>2</sup>56'05.0"W (Supersedes LNM 21/97) 11409 26<sup>th</sup> ed., 04/08/95 LAST LNM 21/97 NAD 83 23/97 Anclote Keys to Crystal River (CGD07) CHANGE Champion Reef Center Buoy to Y can in (Priv maint) 28<sup>2</sup>36'04.5"N 082<sup>2</sup>56'05.0"W (Supersedes LNM 21/97) 11411 10<sup>th</sup> ed., 09/14/96 LAST LNM 18/97 NAD 83 23/97 (TEMP)Tampa Bay to Port Richey (CGD07) ADD Clearwater Hbr Daybeacon "18A" in 27259'24.6"N 082248'02.9"W 11411 10<sup>th</sup> ed., 09/14/96 LAST LNM 18/97 NAD 83 23/97 Tampa Bay to Port Richey (CGD07) RELOCATE Sand Key Lt "4" from (27<sup>2</sup>48'2.384"N, 82<sup>2</sup>46'37.052"W) to (Side A) 27248'02.4"N 082246'37.0"W Sand Key Lt "24" from (27249'51.308"N, 82249'11.761"W) to (Side A) 27249'51.4"N 082249'12.5"W The Narrows Daybeacon "26" from

The Narrows Daybeacon "22" from (27251'25.6"N, 82250'34.2"W) to (Side A) 27251'26.3"N 082250'35.4"W

(21 01 20.0 14, 02 00 04.2 W) to (Olde 11) 21 01 20.0 W 002 00 00.4 W

Clearwater Hbr Lt "12" from

 $(27^257'30.343''N,\,82^248'36.068''W) \ to \ (Side \ B) \ 27^257'30.4''N \ 082^248'36.1''W$ 

(27251'52.314"N, 82250'44.803"W) to (Side A) 27251'53.8"N 082250'47.1"W

Clearwater Hbr Daybeacon "17" from

(27258'48.32"N, 82248'8.879"W) to (Side B) 27258'44.9"N 082248'11.1"W

Ozona Chan Daybeacon "6" from (2824'11.008"N, 82247'18.458"W) to (Side B) 28204'12.2"N 082247'20.2"W St. Joseph Snd Daybeacon "7" from (2820'56.789"N, 82247'56.505"W) to (Side B) 28200'57.0"N 082247'56.3"W Anclote Anch S Entr Daybeacon "3X" from (2828'50.656"N, 82251'5.825"W) to (Side B) 28208'50.3"N 082251'05.6"W Sand Key Daybeacon "8" from (27<sup>2</sup>48'16.182"N, 82<sup>2</sup>47'20.718"W) to (Side B) 27248'15.8"N 082247'20.3"W 11412 37<sup>th</sup> ed., 11/30/96 LAST LNM 18/97 NAD 83 23/97 Tampa Bay and St Joseph Sound (CGD07) RELOCATE Anclote Anch S Entr Daybeacon "3X" from (2828'50.656"N, 82251'5.825"W) to 28208'50.3"N 082251'05.6"W 11414 36<sup>th</sup> ed., 09/28/96 LAST LNM 18/97 NAD 83 23/97 Tampa Bay (Southern Part) (CGD07) RELOCATE Boca Ciega Bay Lt "32" from (27243'57.53"N, 82243'43.353"W) to 27243'57.1"N 082243'43.8"W 11425 31<sup>st</sup> ed., 10/05/96 LAST LNM 19/97 NAD 83 23/97 Charlotte Harbor to Tampa Bay (CGD07) RELOCATE Venice Inl-Siesta Key Lt "48B" from (27213'47.056"N, 82230'43.65"W) to (Side B) 27213'46.8"N 082230'43.4"W Siesta Key-Tampa Bay Lt "23" from (27224'23.821"N, 82238'8.925"W) to (Side B) 27224'23.2"N 082238'08.8"W Siesta Key-Tampa Bay Lt "27" from (27<sup>2</sup>24'55.367"N, 82<sup>2</sup>38'53.866"W) to (Side B) 27224'54.9"N 082238'53.0"W 11442 31st ed., 11/16/96 LAST LNM 22/97 NAD 83 23/97 Sombrero Key to Sand Key (CGD07) RELOCATE Nine-Foot ShI Lt from (24234'8.863"N, 81233'6.916"W) to and **REMOVE PA** 24234'08.8"N 081233'07.4"W 11445 28<sup>th</sup> ed., 04/16/94 LAST LNM 22/97 NAD 83 23/97 Sugarloaf Key - Key West - Bahia Horda Key (CGD07) RELOCATE Nine-Foot ShI Lt from (24234'8.863"N, 81233'6.916"W) to and REMOVE PA 24234'08.8"N 081233'07.4"W

```
11450 6<sup>th</sup> ed., 07/24/93 LAST LNM 09/97 NAD 83
                                                                                                         23/97
         Fowev Rocks to American Shoal
         (CGD07)
         ADD
                            Subm Wr (53 ft Catamaran) in (PA)
         25232'00.0"N 080206'00.0"W
11451 27<sup>th</sup> ed., 02/03/96 LAST LNM 22/97 NAD 83
                                                                                                         23/97
         Miami to Marathon and Florida Bay
         (CGD07)
                            Subm Wr (53 ft Catamaran) in (PA)
         ADD
         25232'00.0"N 080206'00.0"W
    (CGD07)
         RELOCATE
                            Biscayne Chan Daybeacon "4" from
                   (25<sup>2</sup>39'.962"N, 80<sup>2</sup>8'35.946"W) to (Page A)
         25<sup>2</sup>39'06.6"N 080<sup>2</sup>08'36.7"W
    Biscayne Bay Lt "59" from
    (25<sup>2</sup>46'13.397"N, 80<sup>2</sup>10'54.36"W) to (Page D, Inset 1) 25<sup>2</sup>46'13.1"N 080<sup>2</sup>10'54.2"W
    Biscayne Bay Daybeacon "61" from
    (25<sup>2</sup>45'56.967"N, 80<sup>2</sup>10'58.75"W) to (Page D, Inset 1) 25<sup>2</sup>45'55.3"N 080<sup>2</sup>10'57.8"W
    Biscayne Bay Lt "63" from
    (25<sup>2</sup>45'41.528"N, 80<sup>2</sup>11'3.602"W) to and
REMOVE PA (Page D, Inset 1)
                                                                                      25<sup>2</sup>45'41.6"N
080211'03.5"W
    Biscayne Bay Lt "64" from
    (25<sup>2</sup>45'37.21"N, 80<sup>2</sup>11'6.345"W) to (Page A) 25<sup>2</sup>45'37.1"N 080<sup>2</sup>11'06.4"W
    Biscayne Bay Daybeacon "65" from
                   (25<sup>2</sup>45'25.454"N, 80<sup>2</sup>11'3.138"W) to (Page A)
         25245'25.0"N 080211'03.1"W
11451 RELOCATE
                            Biscayne Bay Lt "67" from
(Cont.)
                   (25<sup>2</sup>45'8.955"N, 80<sup>2</sup>11'2.401"W) to (Page A)
         25245'08.6"N 080211'02.4"W
                   Biscayne Bay Daybeacon "69" from
                   (25<sup>2</sup>44'32.119"N, 80<sup>2</sup>11'.052"W) to and
                                                                                      25244'31.3"N
                   REMOVE PA (Page A)
080210'59.8"W
    Biscayne Bay Lt "71" from
    (25<sup>2</sup>44'13.274"N, 80<sup>2</sup>11'.915"W) to (Page A) 25<sup>2</sup>44'13.0"N 080<sup>2</sup>11'00.9"W
    Biscayne Bay Lt "73" from
    (25<sup>2</sup>42'34.52"N, 80<sup>2</sup>10'58.463"W) to (Page A) 25<sup>2</sup>42'34.4"N 080<sup>2</sup>10'58.5"W
    Dinner Key Chan Daybeacon "6" from
    (25<sup>2</sup>43'7.363"N, 80<sup>2</sup>13'17.176"W) to (Bage B, Inset 2) 25<sup>2</sup>43'08.3"N 080<sup>2</sup>13'17.2"W
    Key Biscayne Yacht Club Chan Lt "1" from
    (25<sup>2</sup>41'59.142"N, 80<sup>2</sup>10'46.25"W) to (Page A) 25<sup>2</sup>41'59.1"N 080<sup>2</sup>10'46.4"W
    Key Biscayne Yacht Club Chan Lt "3" from
    (25<sup>2</sup>41'51.537"N, 80<sup>2</sup>10'27.838"W) to (Page A) 25<sup>2</sup>41'51.3"N 080<sup>2</sup>10'27.7"W
```

```
SW ShIs Daybeacon from
     (25<sup>2</sup>41'24.36"N, 80<sup>2</sup>11'1.214"W) to (Page A) 25<sup>2</sup>41'24.1"N 080<sup>2</sup>11'01.5"W
     Biscayne Flats Daybeacon "1" from
     (25<sup>2</sup>40'19.452"N, 80<sup>2</sup>10'59.168"W) to (Page A) 25<sup>2</sup>40'22.0"N 080<sup>2</sup>11'01.7"W
     Biscayne Flats Daybeacon "3" from
     (25<sup>2</sup>39'49.37"N, 80<sup>2</sup>10'59.172"W) to (Page A) 25<sup>2</sup>39'49.7"N 080<sup>2</sup>11'01.2"W
     Shell Key Daybeacon "89" from
     (24°256'23.607"N, 80°39'58.100"W) to (Page E & Page F, Inset 7) 24°256'23.7"N
     080239'58.2"W
     (Supersedes LNM 20/97)
11462 22<sup>nd</sup> ed., 04/13/96 LAST LNM 22/97 NAD 83
                                                                                                         23/97
         Fowey Rocks to Alligator Reef
         (CGD07)
         ADD
                             Subm Wr (53 ft Catamaran) in (PA)
         25232'00.0"N 080206'00.0"W
11463 14<sup>th</sup> ed., 11/26/94 LAST LNM 22/97 NAD 83
                                                                                                         23/97
         Sands Key to Matecumbe
         (CGD07)
         RELOCATE
                            Shell Key Daybeacon "89" from
                   (24256'23.607"N, 80239'58.100"W) to
         24256'23.7"N 080239'58.2"W
     (Supersedes LNM 20/97)
11465 31<sup>st</sup> ed., 05/05/96 LAST LNM 19/97 NAD 83
                                                                                                         23/97
         Miami to Elliot Key
         (CGD07)
         RELOCATE
                            Biscayne Chan Daybeacon "4" from
                   (25<sup>2</sup>39'.962"N, 80<sup>2</sup>8'35.946"W) to
         25<sup>2</sup>39'06.6"N 080<sup>2</sup>08'36.7"W
     Biscayne Bay Lt "59" from
     (25<sup>2</sup>46'13.397"N, 80<sup>2</sup>10'54.36"W) to 25<sup>2</sup>46'13.1"N 080<sup>2</sup>10'54.2"W
     Biscayne Bay Daybeacon "61" from
     (25<sup>2</sup>45'56.967"N, 80<sup>2</sup>10'58.75"W) to 25<sup>2</sup>45'55.3"N 080<sup>2</sup>10'57.8"W
     Biscayne Bay Lt "63" from
     (25<sup>2</sup>45'41.528"N, 80<sup>2</sup>11'3.602"W) to 25<sup>2</sup>45'41.6"N 080<sup>2</sup>11'03.5"W
     Biscayne Bay Lt "64" from
     (25<sup>2</sup>45'37.21"N, 80<sup>2</sup>11'6.345"W) to 25<sup>2</sup>45'37.1"N 080<sup>2</sup>11'06.4"W
     Biscayne Bay Daybeacon "65" from
     (25<sup>2</sup>45'25.454"N, 80<sup>2</sup>11'3.138"W) to 25<sup>2</sup>45'25.0"N 080<sup>2</sup>11'03.1"W
     Biscayne Bay Lt "67" from
     (25<sup>2</sup>45'8.955"N, 80<sup>2</sup>11'2.401"W) to 25<sup>2</sup>45'08.6"N 080<sup>2</sup>11'02.4"W
     Biscayne Bay Daybeacon "69" from
     (25244'32.119"N, 80211'.052"W) to and
```

```
REMOVE PA
```

25244'31.3"N 080210'59.8"W

```
Biscayne Bay Lt "71" from
```

(25<sup>2</sup>44'13.274"N, 80<sup>2</sup>11'.915"W) to 25<sup>2</sup>44'13.0"N 080<sup>2</sup>11'00.9"W

Biscayne Bay Lt "73" from

(25<sup>2</sup>42'34.52"N, 80<sup>2</sup>10'58.463"W) to 25<sup>2</sup>42'34.4"N 080<sup>2</sup>10'58.5"W

Dinner Key Chan Daybeacon "6" from

(25<sup>2</sup>43'7.363"N, 80<sup>2</sup>13'17.176"W) to 25<sup>2</sup>43'08.3"N 080<sup>2</sup>13'17.2"W

Key Biscayne Yacht Club Chan Lt "1" from

(25<sup>2</sup>41'59.142"N, 80<sup>2</sup>10'46.25"W) to 25<sup>2</sup>41'59.1"N 080<sup>2</sup>10'46.4"W

Key Biscayne Yacht Club Chan Lt "3" from

(25241'51.537"N, 80210'27.838"W) to 25241'51.3"N 080210'27.7"W

SW Shls Daybeacon from

(25<sup>2</sup>41'24.36"N, 80<sup>2</sup>11'1.214"W) to 25<sup>2</sup>41'24.1"N 080<sup>2</sup>11'01.5"W

Biscayne Flats Daybeacon "1" from

(25<sup>2</sup>40'19.452"N, 80<sup>2</sup>10'59.168"W) to 25<sup>2</sup>40'22.0"N 080<sup>2</sup>11'01.7"W

Biscayne Flats Daybeacon "3" from

(25<sup>2</sup>39'49.37"N, 80<sup>2</sup>10'59.172"W) to 25<sup>2</sup>39'49.7"N 080<sup>2</sup>11'01.2"W

11466 32<sup>nd</sup> ed., 11/16/96 LAST LNM 20/97 NAD 83

Jupiter Inlet to Fowey Rocks

(CGD07)

RELOCATE Biscayne Chan Daybeacon "4" from

(25<sup>2</sup>39'.962"N, 80<sup>2</sup>8'35.946"W) to

25239'06.6"N 080208'36.7"W

Biscayne Flats Daybeacon "1" from

 $(25^240'19.452"N,\,80^210'59.168"W)$  to  $25^240'22.0"N\,080^211'01.7"W$ 

11467 33<sup>rd</sup> ed., 12/14/96 LAST LNM 20/97 NAD 83

West Palm Beach to Miami

(CGD07)

RELOCATE New River Snd Lt "13" from

(26<sup>2</sup>6'39.811"N, 80<sup>2</sup>6'36.599"W) to (Side A, Inset 1)

26206'39.6"N 080206'36.2"W

Biscayne Chan Daybeacon "4" from

(25<sup>2</sup>39'.962"N, 80<sup>2</sup>8'35.946"W) to (Side B) 25<sup>2</sup>39'06.6"N 080<sup>2</sup>08'36.7"W

Biscayne Bay Daybeacon "4A" from

(25<sup>2</sup>54'33.01"N, 80<sup>2</sup>7'34.723"W) to (Side B, Inset 2)

25254'32.9"N 080207'34.7"W

11467 RELOCATE Biscayne Bay Lt "5" from

(Cont.) (25<sup>2</sup>54'32.738"N, 80<sup>2</sup>7'31.827"W) to (Side B, Inset 2)

25254'32.6"N 080207'32.0"W

Biscayne Bay Daybeacon "6" from

23/97

23/97

```
25254'26.4"N 080207'38.3"W
     Biscayne Bay Daybeacon "6A" from
     (25<sup>2</sup>54'14.694"N, 80<sup>2</sup>7'47.551"W) to (Side B, Inset 2) 25<sup>2</sup>54'14.7"N 080<sup>2</sup>07'47.4"W
     Biscayne Bay Lt "59" from
     (25<sup>2</sup>46'13.397"N, 80<sup>2</sup>10'54.36"W) to (Side B, Inset 2) 25<sup>2</sup>46'13.1"N 080<sup>2</sup>10'54.2"W
     Biscayne Bay Daybeacon "61" from
     (25<sup>2</sup>45'56.967"N, 80<sup>2</sup>10'58.75"W) to (Side B, Inset 2) 25<sup>2</sup>45'55.3"N 080<sup>2</sup>10'57.8"W
     Biscayne Bay Lt "63" from
     (25<sup>2</sup>45'41.528"N, 80<sup>2</sup>11'3.602"W) to (Side B, Inset 2) 25<sup>2</sup>45'41.6"N 080<sup>2</sup>11'03.5"W
     Biscayne Bay Lt "64" from
     (25<sup>2</sup>45'37.21"N, 80<sup>2</sup>11'6.345"W) to (Side B, Inset 2) 25<sup>2</sup>45'37.1"N 080<sup>2</sup>11'06.4"W
     Biscayne Bay Daybeacon "65" from
     (25<sup>2</sup>45'25.454"N, 80<sup>2</sup>11'3.138"W) to (Side B) 25<sup>2</sup>45'25.0"N 080<sup>2</sup>11'03.1"W
     Biscayne Bay Lt "67" from
     (25<sup>2</sup>45'8.955"N, 80<sup>2</sup>11'2.401"W) to (Side B) 25<sup>2</sup>45'08.6"N 080<sup>2</sup>11'02.4"W
     Biscayne Bay Daybeacon "69" from
     (25<sup>2</sup>44'32.119"N, 80<sup>2</sup>11'.052"W) to and
REMOVE PA (Side B)
                                                                         25244'31.3"N 080210'59.8"W
     Biscayne Bay Lt "71" from
     (25<sup>2</sup>44'13.274"N, 80<sup>2</sup>11'.915"W) to (Side B) 25<sup>2</sup>44'13.0"N 080<sup>2</sup>11'00.9"W
     Dinner Key Chan Daybeacon "6" from
     (25<sup>2</sup>43'7.363"N, 80<sup>2</sup>13'17.176"W) to (Side B, Inset 4) 25<sup>2</sup>43'08.3"N 080<sup>2</sup>13'17.2"W
     Key Biscayne Yacht Club Chan Lt "1" from
                     (25<sup>2</sup>41'59.142"N, 80<sup>2</sup>10'46.25"W) to (Side B)
          25<sup>2</sup>41'59.1"N 080<sup>2</sup>10'46.4"W
11468 33<sup>rd</sup> ed., 05/04/96 LAST LNM 19/97 NAD 83
                                                                                                                   23/97
          Miami Harbor
          (CGD07)
          RELOCATE
                               Biscayne Bay Lt "59" from
                     (25<sup>2</sup>46'13.397"N, 80<sup>2</sup>10'54.36"W) to
          25<sup>2</sup>46'13.1"N 080<sup>2</sup>10'54.2"W
     Biscayne Bay Daybeacon "61" from
     (25<sup>2</sup>45'56.967"N, 80<sup>2</sup>10'58.75"W) to 25<sup>2</sup>45'55.3"N 080<sup>2</sup>10'57.8"W
     Biscayne Bay Lt "63" from
     (25<sup>2</sup>45'41.528"N, 80<sup>2</sup>11'3.602"W) to 25<sup>2</sup>45'41.6"N 080<sup>2</sup>11'03.5"W
     Biscayne Bay Lt "64" from
     (25<sup>2</sup>45'37.21"N, 80<sup>2</sup>11'6.345"W) to 25<sup>2</sup>45'37.1"N 080<sup>2</sup>11'06.4"W
     Biscayne Bay Daybeacon "65" from
     (25<sup>2</sup>45'25.454"N, 80<sup>2</sup>11'3.138"W) to 25<sup>2</sup>45'25.0"N 080<sup>2</sup>11'03.1"W
```

(25<sup>2</sup>54'26.482"N, 80<sup>2</sup>7'38.489"W) to (Side B, Inset 2)

Biscayne Bay Lt "67" from

(25<sup>2</sup>45'8.955"N, 80<sup>2</sup>11'2.401"W) to 25<sup>2</sup>45'08.6"N 080<sup>2</sup>11'02.4"W

Biscayne Bay Daybeacon "69" from

(25244'32.119"N, 80211'.052"W) to and

**REMOVE PA** 

25244'31.3"N 080210'59.8"W

11470 31<sup>st</sup> ed., 11/23/96 LAST LNM 20/97 NAD 83

23/97

Ft. Lauderdale to Port Everglades

(CGD07)

RELOCATE New River Snd Lt "13" from (26<sup>2</sup>6'39.811"N, 80<sup>2</sup>6'36.599"W) to 26<sup>2</sup>06'39.6"N 080<sup>2</sup>06'36.2"W

11472 28<sup>th</sup> ed., 08/05/95 LAST LNM 21/97 NAD 83

23/97

Palm Shores to West Palm Beach (CGD07)

RELOCATE Lake Worth N Lt "27" from (26<sup>2</sup>49'36.55"N, 80<sup>2</sup>3'14.737"W) to (Side B)

26<sup>2</sup>49'36.6"N 080<sup>2</sup>03'14.6"W

Lake Worth N Daybeacon "28" from

(26<sup>2</sup>49'29.06"N, 80<sup>2</sup>3'15.808"W) to (Side B) 26<sup>2</sup>49'29.4"N 080<sup>2</sup>03'15.5"W

Lake Worth N Daybeacon "29" from

(26<sup>2</sup>49'22.239"N, 80<sup>2</sup>3'9.719"W) to (Side B) 26<sup>2</sup>49'22.6"N 080<sup>2</sup>03'09.3"W

Lake Worth N Daybeacon "30" from

(26<sup>2</sup>48'51.768"N, 80<sup>2</sup>3'3.62"W) to (Side B) 26<sup>2</sup>48'51.4"N 080<sup>2</sup>03'02.5"W

Lake Worth N Lt "30A" from

(26248'15.863"N, 8022'52.481"W) to (Side B) 26248'16.0"N 080202'52.1"W

Lake Worth N Daybeacon "34" from

(26248'15.584"N, 8022'50.432"W) to (Side B) 26248'16.0"N 080202'50.0"W

Lake Worth N Daybeacon "32" from

(26<sup>2</sup>47'58.712"N, 80<sup>2</sup>2'51.011"W) to (Side B) 26<sup>2</sup>47'57.6"N 080<sup>2</sup>02'50.0"W

Lake Worth N Daybeacon "33" from

(26<sup>2</sup>47'57.181"N, 80<sup>2</sup>2'48.623"W) to (Side B) 26<sup>2</sup>47'57.6"N 080<sup>2</sup>02'48.1"W

Lake Worth N Lt "34" from

(26<sup>2</sup>47'35.708"N, 80<sup>2</sup>2'48.558"W) to (Side B) 26<sup>2</sup>47'35.0"N 080<sup>2</sup>02'47.8"W

Lake Worth N Lt "36" from

(26<sup>2</sup>47'7.252"N, 80<sup>2</sup>2'47.457"W) to (Side B & Side B, Inset 2) 26<sup>2</sup>47'12.8"N 080<sup>2</sup>02'45.5"W

Lake Worth N Daybeacon "37" from

(26247'9.873"N, 8022'43.473"W) to and

REMOVE PA (Side B & Side B, Inset 2) 080<sup>2</sup>02'43.0"W

26<sup>2</sup>47'09.6"N

Lake Worth N Lt "39" from

(26<sup>2</sup>46'47.995"N, 80<sup>2</sup>2'42.697"W) to (Side B & Side B, Inset 2) 26<sup>2</sup>46'48.1"N 080<sup>2</sup>02'42.2"W Lake Worth S Daybeacon "2A" from (26<sup>2</sup>45'43.873"N, 80<sup>2</sup>2'57.599"W) to (Side B & Side B, Inset 2) 26<sup>2</sup>45'43.7"N 080<sup>2</sup>02'57.7"W Lake Worth S Daybeacon "4" from (26<sup>2</sup>45'16.542''N, 80<sup>2</sup>2'54.197''W) to (Side B & Side B, Inset 2) 26<sup>2</sup>45'16.6"N 080<sup>2</sup>02'55.0"W 11489 30<sup>th</sup> ed., 01/20/96 LAST LNM 21/97 NAD 83 23/97 St. Simons Island Sound - Tolomato River (CGD07) CHANGE St. Andrews Snd Buoy "11" to - Buoy "7" in (Side A) 30258'35.8"N 081222'37.2"W St. Andrews Snd Buoy "13" to - Buoy "9" in (Side A) 30258'54.9"N 081223'05.2"W 11490 14<sup>th</sup> ed., 03/30/96 LAST LNM 41/96 NAD 83 23/97 Approaches to St. Johns River (NOS SILVER SPRING) purple racon symbol to buoy "STJ" at ADD 30<sup>2</sup>23'35.4"N 081<sup>2</sup>19'08.4"W 11491 29<sup>th</sup> ed., 01/04/97 LAST LNM 22/97 NAD 83 23/97 St. Johns River (Atlantic Ocean to Jacksonville) (NOS SILVER SPRING) ADD purple racon symbol to buoy "STJ" at (Side A) 30223'35.4"N 081219'08.4"W 11502 26<sup>th</sup> ed., 07/06/96 LAST LNM 21/97 NAD 83 23/97 Doboy Sound to Fernandina (CGD07) St. Andrews Snd Buoy "2", R nun in ADD 30256'31.7"N 081221'28.1"W (CGD07) CHANGE St. Andrews Snd Buoy "3" to - Buoy "1", G can in 30255'35.8"N 081220'42.3"W St. Andrews Snd Buoy "7" to - Buoy "3" and RELOCATE from (30257'05.8"N 081221'24.3"W) to 30257'06.0"N 081221'33.1"W St. Andres Snd Buoy "9" to - Buoy "5" and RELOCATE from (30257'46.8"N 081221'46.3"W) to 30<sup>2</sup>57'46.4"N 081<sup>2</sup>21'51.6"W St. Andrews Snd Buoy "11" to - Buoy "7" in 30258'35.8"N 081222'37.2"W St. Andrews Snd Buoy "13" to - Buoy "9" in 30258'54.9"N 081223'05.2"W (CGD07) DELETE St. Andrews Snd Buoy "5" from 30256'23.8"N 081221'15.3"W

```
11504 13<sup>th</sup> ed., 01/26/91 LAST LNM 21/97 NAD 83
                                                                                       23/97
       St. Andrew Sound and Satilla River
       (CGD07)
       ADD
                       St. Andrews Snd Buoy "2", R nun in
       30256'31.7"N 081221'28.1"W
   (CGD07)
                       St. Andrews Snd Buoy "3" to - Buoy "1",G can in 30255'35.8"N
   CHANGE
   081220'42.3"W
   St. Andrews Snd Buoy "7" to - Buoy "3" and
   RELOCATE from
   (30257'05.8"N 081221'24.3"W) to 30257'06.0"N 081221'33.1"W
   St. Andres Snd Buoy "9" to - Buoy "5" and
   RELOCATE from
               (30257'46.8"N 081221'46.3"W) to
       30257'46.4"N 081221'51.6"W
               St. Andrews Snd Buoy "11" to - Buoy "7" in
       30258'35.8"N 081222'37.2"W
               St. Andrews Snd Buoy "13" to - Buoy "9" in
       30258'54.9"N 081223'05.2"W
   (CGD07)
                       St. Andrews Snd Buoy "5" from
       30256'23.8"N 081221'15.3"W
11507 28<sup>th</sup> ed., 08/03/96 LAST LNM 21/97 NAD 83
                                                                                       23/97
       SC - GA - Beaufort Riv - St. Simons Sound
       RELOCATE
                       Elba Is Cut Daybeacon "8" from
               (3223'55.385"N, 80259'26.831"W) to (Side A)
       32203'55.5"N 080259'27.0"W
   Vernon River Daybeacon "82" from
   (31253'34.886"N, 8125'31.981"W) to (Side A) 31253'34.7"N 081205'31.9"W
   Old Teakettle Cr Daybeacon "168" from
               (31<sup>2</sup>27'41.287"N, 81<sup>2</sup>19'26.562"W) to (Side B)
       31<sup>2</sup>27'40.7"N 081<sup>2</sup>19'26.4"W
11509 25<sup>th</sup> ed., 08/17/96 LAST LNM 21/97 NAD 83
                                                                                       23/97
       Tybee Island to Doboy Sound
       (CGD07)
       RELOCATE
                       Vernon River Daybeacon "82" from
               (31253'34.886"N, 8125'31.981"W) to
       31253'34.7"N 081205'31.9"W
11510 16<sup>th</sup> ed., 01/28/95 LAST LNM 21/97 NAD 83
                                                                                       23/97
       Sapelo Sound and Doboy Sound
       (CGD07)
       RELOCATE
                       Old Teakettle Cr Daybeacon "168" from
               (31<sup>2</sup>27'41.287"N, 81<sup>2</sup>19'26.562"W) to
       31227'40.7"N 081219'26.4"W
11512 54<sup>th</sup> ed., 09/21/96 LAST LNM 21/97 NAD 83
                                                                                       23/97
```

Savannah River and Wassaw Sound (CGD07) RELOCATE Elba Is Cut Daybeacon "8" from (3223'55.385"N, 80259'26.831"W) to 32203'55.5"N 080259'27.0"W Vernon River Daybeacon "82" from (31253'34.886"N, 8125'31.981"W) to 31253'34.7"N 081205'31.9"W 11516 28<sup>th</sup> ed., 04/16/97 NEW EDITION 11XHA11516 NAD 83 23/97 Port Royal Sound and Island Passages (NOS SILVER SPRING) (New edition due to changes in hydrography and various general changes.) 1:40.000/\$14.00 11520 36<sup>th</sup> ed., 11/16/96 LAST LNM 12/97 NAD 83 23/97 Cape Hatteras to Charleston (CGD07) ADD Subm Wr (75 ft F/V PENNEYS PRIDE) in (PA) 32252'24.0"N 079232'12.0"W 11521 23<sup>rd</sup> ed., 03/29/97 NEW EDITION 11AHA11521 NAD 83 23/97 (TEMP)Charleston Harbor and Approaches (NOS SILVER SPRING) (New edition due to various genderal changes.) 1:80,000/Loran-C/\$14.00 (CGD07) 16/97 Folly River Daybeacon "11" to - Buoy "11" in CHANGE 32238'05.1"N 079259'17.2"W 11521 23<sup>rd</sup> ed., 03/29/97 NEW EDITION 11AHA11521 NAD 83 23/97 Charleston Harbor and Approaches (NOS SILVER SPRING) (New edition due to various genderal changes.) 1:80,000/Loran-C/\$14.00 (NOS SILVER SPRING) (CL-1384/96) 17/97 black dotted lines, blue tint, and label Obstn Fish ADD Haven (auth min depth 20 ft) joining 32225'31.8"N 080212'03.0"W to 32<sup>2</sup>25'01.8"N 080<sup>2</sup>12'03.0"W to 32225'01.8"N 080211'30.6"W to 32225'31.8"N 080211'30.6"W (NOS SILVER SPRING) (CL-1384/96) DELETE depth: 47 feet at 32225'18.0"N 080211'44.0"W (NOS SILVER SPRING) (CL-524/96) 18/97 ADD dotted danger circle with 43 ft depth, blue tint.

at

20/97

and label: Obstn Coral Head

(NOS SILVER SPRING) (CL-1386/96)

32241'15.3"N 079244'07.9"W

ADD black dotted lines joining 32<sup>2</sup>39'14.0"N 079<sup>2</sup>56'22.0"W to 32239'16.0"N 079256'17.0"W to 32239'12.0"N 079256'14.0"W to and label: Obstn Fish Haven 32239'09.0"N (auth min 10 ft) 079<sup>2</sup>56'19.0"W (CGD07) CHANGE Ft Sumer Rge Front Lt to FI (2) 5s, continuous operation 32244'50.6"N Day/Night in 079251'45.8"W Ft Sumter Rge Rear Lt to continuous operation Day/Night in 32245'18.3"N 079252'44.0"W (CGD07) 21/97 Ft. Sumter Rge Front Lt to FI 2.5s in CHANGE 32244'50.6"N 079251'45.8"W 11523 17<sup>th</sup> ed., 03/29/97 NEW EDITION 11AHA11523 NAD 83 23/97 Charleston Harbor Entrance (NOS SILVER SPRING) (New edition due to changes in hydrography and various general changes.) 1:20,000/\$14.00 (NOS SILVER SPRING) (CL-7/97) depth legend to: 8 FT JUL 1994 - AUG 1996 CHANGE at 32<sup>2</sup>47'04.0"N 079<sup>2</sup>53'09.0"W (NOS SILVER SPRING) (CL-524/97) 18/97 and label: Obstn Coral Head at 32241'15.3"N 079244'07.9"W 20/97 (CGD07)

079<sup>2</sup>51'45.8"W

CHANGE

Ft Sumter Rge Rear Lt to continuous operation Day/Night in

Ft Sumer Rge Front Lt to FI (2) 5s, continuous operation

32245'18.3"N 079252'44.0"W

Day/Night in

(CGD07) 21/97

CHANGE Ft. Sumter Rge Front Lt to FI 2.5s in

32244'50.6"N 079251'45.8"W

11531 18<sup>th</sup> ed., 07/30/94 LAST LNM 20/97 NAD 83

23/97

32244'50.6"N

Winyah Bay Entrance to Isle of Palms

(CGD07)

ADD Subm Wr (75 ft F/V PENNEYS PRIDE) in (PA)

32252'24.0"N 079232'12.0"W

## V. NEW ADVANCE NOTICE

None.

#### VI. NEW PROPOSED CHANGES

None.

#### VII. NEW GENERAL INFORMATION

#### A. NEW BRIDGE INFORMATION

FLORIDA-INTRACOASTAL WATERWAY-HILLSBORO RIVER-BISCAYNE CREEK: Special Bridge Notice.

The Coast Guard has received a request from the Middlesex Corporation, contractor for the Florida Department of Transportation, to allow a temporary change in the operating regulations for the East Sunrise Boulevard Drawbridge across the Intracoastal Waterway, mile 1062.6, Fort Lauderdale, Broward County, Florida, to accommodate structural repairs.

If authorized, the proposal would allow only the west spans of the East Sunrise Boulevard Drawbridge to open to vessel traffic from 8:00 a.m., June 16, 1997, to 6:00 p.m., June 21, 1997. The East Sunrise Boulevard Drawbridge provides a vertical clearance of 25 feet above mean high water in the closed position and a horizontal clearance of 90 feet between fenders. With one leaf in the closed position, a horizontal clearance of approximately 44 feet remains available for navigation.

The Coast Guard is seeking comments on this proposed closure period and the effect it would have on navigation. Comments should be sent to the address on the cover of this notice and should be mailed to arrive no later than June 12, 1997. If you're unable to respond in writing you can comment by calling Brodie Rich at (305) 536-5117.

Chart: 11467 CG File: 2754

FLORIDA-INTRACOASTAL WATERWAY-HILLSBORO RIVER-BISCAYNE CREEK: Special Bridge Notice.

The Coast Guard has received a request from the City of Hollywood Police Department to allow a temporary change in the operating regulations for the Dania Beach Boulevard, Sheridan Street, and Hollywood Boulevard Drawbridges across the Intracoastal Waterway (Miles 1069.4, 1070.5, and 1072.2), at Holywood, Broward County, Florida, to accommodate the annual Fourth of July fireworks event.

If authorized, the proposal would allow these three drawbridges not to open to vessel traffic from 9:30 p.m. to 11:30 p.m. on Thursday, July 4, 1997, except that the Dania Beach Boulevard Drawbridew ill open at 10:15 p.m., the Sheridan Street Drawbridge will open at 10:30 p.m., and the Hollywood Boulevard Drawbridge will open at 10:45 p.m. The minimum vertical clearance of these three drawbridges is 22 feet above mean high water in the closed position and a horizontal clearance of 90 feet between fenders.

FLORIDA-INTRACOASTAL WATERWAY-HILLSBORO RIVER-BISCAYNE CREEK: Special Bridge Notice. (Cont.)

The Coast Guard is seeking comments on this proposed closure period with the designated interim openings for each drawbridge and the effect it would have on navigation. Comments should be sent to the address on the cover of this notice and should be mailed to arrive no later than June 23, 1997. If you're unable to respond in writing you can comment by calling Brodie Rich at (305) 536-5117.

Chart: 11467 CG Files: 2826/3080/2899

FLORIDA-INTRACOASTAL WATERWAY-BISCAYNE BAY-MIAMI RIVER: Special Bridge Notice.

The Coast Guard has received a request from the Florida Department of Transportation in Miami to allow a temporary change in the operating regulations for the Northwest 1<sup>th</sup> Avenue Drawbridge across the Miami River, mile 2.1 at Miami, Dade County, Florida, to accommodate mechanical drawbridge repairs.

If authorized, this proposal would allow the Northwest 1½ Avenue Drawbridge not to open for vessel traffic from 8:00 p.m. on Sunday, June 29, 1997, through 5:00 a.m. on Monday, June 30, 1997. However, the drawbridge will open is a 30-minute advance notification is provided by the vessel requesting the opening. The vertical clearance of this drawbridge in the closed position is 17 feet above mean high water is the closed position and a horizontal clearance of 94 feet between fenders.

The Coast Guard is seeking comments on this proposed closure period for the drawbridge and the effect it would have on navigation. Comments should be sent to the address on the cover of this notice and should be mailed to arrive no later than June 19, 1997. If you're unable to respond in writing you can comment by calling Brodie Rich at (305) 536-5117.

#### B. MISCELLANEOUS INFORMATION

SOUTH CAROLINA-CHARLESTON ENTRANCE-CHARLESTON HARBOR: Boring Samples Operations.

The U.S. Army Corps of Engineers Charleston advises the jack-up barge EXPLORER is conducting boring samples operations in Charleston Harbor until Jun 21, 1997. The barge can be contacted on VHF-FM channels 13 or 16 for passing information. The Army Corps of Engineers requests minimum wake around the barge during this operation.

Ref: BNM 576-97-D7 Chart: 11523

GEORGIA-SAVANNAH RIVER-FRONT CHANNEL: Dredging Operations.

The U.S. Army Corps of Engineers Savannah advises the dredge STUART is conducting maintenance dredging operations between CITY FRONT CHANNEL LIGHT 62 (LLNR 4410) to the U.S. Army Corps of Engineers Depot, Hutchinson Island, Georgia, until June 10, 1997.

Ref: BNM 281-97-CHA Chart: 11514

FLORIDA-CHARLOTTE HARBOR TO TAMPA BAY-NEW PASS: Dredging Operations.

The dredge HENDRY NO. 4 will be performing maintenance dredging of New Pass and pumping sand onto the beach, from June 15 to August 15, 1997, 24 hours-a-day, seven days-a-week. Numerous barges, pipelines, and other floating equipment are present in this area. Pipelines will be submerged on the bottom in the area of the pass. The dredge can be contacted on VHF-FM channels 13, 16, and 79, or additional information can be obtained by calling (813) 831-1211.

#### Chart: 11425

FLORIDA-TAMPA BAY-TAMPA BAY CUT I TO N ST. PETERSBURG: Dredging Operations.

Florida Dredge and Dock Incorporated is conducting dredging operations in Tampa Bay Cut I, K, L, M, and North St. Petersburg for approximately six weeks. Material is being transported up Tampa Bay Cut P for off loading in the vicinity of Old Weedon Island Bridge.

**Chart: 11413** 

SOUTH CAROLINA-INTRACOASTAL WATERWAY-LITTLE RIVER INLET TO CHARLESTON HARBOR: Clearing and Snagging Operations.

The U.S. Army Corps of Engineers snag boat SNELL is perfoming clearing and snagging operations at various locations in the Intracoastal Waterway between Little River Inlet and Charleston Harbor until approximately July 15, 1997. The snag boat can be contacted on VHF-FM channels 13 or 16 for additional infomation.

Chart: 11534, 11518

# VIII. LIGHT LIST CORRECTIONS

(1) (2) (3) (4) (5) (6) (7) (8)

No. Name and Location Position Characteristic Ht Rng Structure Remarks

None.

## IX. ADDITIONAL ENCLOSURES

Enclosure (1) Report of Channel Conditions for Palm Beach Harbor, Palm Beach County, Florida.

Enclosure (2) Report of Channel Conditions for Ponce de Leon Inlet, Volusia County, Florida.

Enclosure (3) Report of Channel Conditions for Mayaquez Harbor, Puerto Rico.

John W. Lockwood Rear Admiral, U.S. Coast Guard Commander, Seventh Coast Guard District